



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report Minerals Regulatory Program

Supervisor SW

October 4, 2007

**Mine Name:** Black Rock

**Operator Name:** Allroc Fine Aggregates, LC

**Permit number:** M/027/112-0088

**Inspection Date:** September 28, 2007

**Time:** 11:00 am

**Inspector(s):** Lynn Kunzler, DOGM

**Other Participants:** none

**Mine Status:** Unpermitted / Active

#### Elements of Inspection

1. Permits, Revisions, Transfer, Bonds
2. Public Safety (shafts, adits, trash, signs, highwalls)
3. Protection of Drainages / Erosion Control
4. Deleterious Material
5. Roads (maintenance, surfacing, dust control, safety)
6. Concurrent Reclamation
7. Backfilling/Grading (trenches, pits, roads, highwalls,
8. Soils
9. Revegetation

Evaluated	Comment	Enforcement
<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

#### Purpose of Inspection:

This was a routine inspection while in the area.

#### Inspection Summary:

While there was no mining activity at this site during the inspection, this site is considered active as per evidence observed of recent activity.

This site was originally permitted by Rocanville Corporation on June 9, 2000, as a small mining operation. On February 3, 2005 a Notice for a large mining operation was received which received tentative approval on December 14, 2005, pending submittal of the reclamation surety and contract. The annual permit fee was not paid for 2006 or 2007 (total delinquent amount is \$1000). This site was put in suspended status March 15, 2007 for failure to pay the annual fee. All mining activity was to cease until permit fees are paid and reclamation surety posted. Recently, the Division received an incomplete transfer form to transfer this permit from Rocanville Corp. to Allroc fine Aggregates, LC.

During this inspection, A GPS survey was conducted to determine the current disturbed acreage. Photos were taken to document site conditions.

#### Conclusions and Recommendations:

Results of the GPS survey show 5.7 acres of mining related disturbance (access road not included). This site is not in compliance with the Utah Mined Land Reclamation Act and regulatory rules. Cessation of operations is warranted until the site is permitted as a large mining operation, past permit fees are paid, and an adequate reclamation surety is provided and approved. Enforcement action is warranted against Allroc, since they have apparently resumed mining operations at a suspended site prior to obtaining approval or posting the required reclamation surety.

**Inspector's Signature** 3/3/7

LK:pb

O:\M027-Millard\M0270112-Blackrock\inspections\Insp-09282007.doc

*This inspection report is not the final report for this date, though signed. See Forpro.*